

# Service Bulletin

**Subject: PHU Air Heater Replacement in Stores With  
240 Volt AC Incoming Power**

**02/03/2017**

Merco legacy or the new MercoMax cabinets in 2x3 or 2x4 configurations (model numbers: MHCFA23, MHCFA24, MHB23 MHB24) operating on more than 230V will require a 450 watt air heater (8263391) to replace a failed air heater.

